MTA C&D SMALL BUSINESS PROGRAM

2023 COMPLETED PROJECTS

Agency	No of Projects	Type of Projects
NYCT	38	 Stairs: 21 PID: 7 Remediation Sys: 2 Comm Rm: 3 Emergency Exits: 1 Vents: 1 Masonry: 1 Roof repair: 2
NYCT/DOB	5	• Bus: 5
B&T	6	 Flood mitigation: 1 Tunnel ceiling preservation: 4 Bridge preservation: 1
LIRR	3	 Yard EIC Fit Out: 1 Tunnel Structural Work: 1 Loading Dock Repair and Paving: 1

NYCT STAIR PROJECTS (TIER-1)

Street Stair
Repairs S/P2 at
28th Street
Station,
Broadway/4th
Avenue Line,
BMT, in the
Borough of
Manhattan

Contractor: GUR Contracting, Corp












BEFORE

Stair Repairs at
Parkside Ave
Station, Brighton
Beach Line
(BMT), in the
Borough of
Brooklyn

Contractor: Popular Services Inc.







Stair Repairs at Ralph Avenue Station, Fulton Street

Line (IND), in the Borough of Brooklyn

Contractor:

RK Best Construction Inc.







Street Stair Repairs S2 & M2 at 205th Street Station, Broadway Line, BMT, in the Borough of the Bronx

Contractor: ZK Ideal Construction Corp








Street Stair
Repairs S1,
P1A/P1B at
Dyckman
Street Station,
8th Avenue
Line, IND, in
the Borough of
Manhattan


Contractor: Yam Contractor Corp












Street Stair
Repairs S1,
P1A/P1B at
Dyckman
Street Station,
8th Avenue
Line, IND, in
the Borough of
Manhattan

Contractor: Eagle Vision Construction Inc










Stair Repairs
S3, M3A/B at
Grand Ave
Station,
Queens
Boulevard Line
(IND), in the
Borough of
Queens

Contractor: IKNA Construction














Stair Repairs S2, M2A/B AT Elmhurst Avenue

Station, Queens Boulevard Line (IND), in the Borough of Queens

Contractor: Innovative Construction















Stair Repairs S6, M6A/B/C at Queens Plaza Station,

Queens
Boulevard
Line (IND), in
the Borough
of Queens

Contractor: All Aces Corp









Stair Repairs
S3A/B, M9A/B at
Jamaica Center Parsons Station,
Archer Avenue
Line (IND), in the
Borough of
Queens

Contractor: Capital Projects, Inc








STREET STAIR
REPAIRS S1,
P1A/B AT
23RD STREET
STATION
B'WAY/7TH
AVE. LINE, IRT,
IN THE
BOROUGH OF
MANHATTAN

Contractor: Antanas Construction









Stair Repairs S1, M1 at Grand Army Plaza Station on Eastern Parkway Line (IRT), in the Borough of Brooklyn

Contractor: Yam Contractor Corp












Stair Repairs S5, M5 at 3rd Avenue – 138th Street Station on Pelham Line (IRT), in the Borough of the Bronx


Contractor: Eagle Vision Construction, Inc












Stair Repairs
S4, P4 at Spring
Street Station
on Lexington
Avenue Line
(IRT), in the
Borough of
Manhattan

Contractor: Antanas Construction











Stair Repairs S1A/B, M1A/B at Woodlawn Station, Jerome Avenue Line (IRT), in the Borough of the Bronx


Contractor: Sherwani Contracting Inc.















Stair Repairs
S4, MA4A/B at
Vernon
Boulevard –
Jackson
Avenue Station
on Flushing
Line (IRT), in
the Borough of
Queens

Contractor: Atarch Group LLC



NYCT STAIR PROJECTS (TIER -2)

Street Stair Repairs S4 A/B, S5 A/B, S6 A/B/C/D at Union Square Station, Broadway/4th Ave. line (BMT) in the Borough of Manhattan

Contractor: Sega Contracting Corporation







Stair Repairs S14/M14, S3/M3AB at Jamaica – 179th Street Station on Queens Boulevard Line (IND), in the Borough of Queens

Contractor: Skyview Construction Group Inc










Stair Repairs S4, M4A/B, S5, M5A/B at 169th Street

Station, Queens Boulevard Line (IND), in the

Borough of Queens

Contractor: On Top Renovation







SBP NYCT Tier – 2 A-37724

Rehabilitation of Emergency Exit #210: Stair Repairs S1, S2, S3, M1, M2A/B M3A/B, M4 at Sutphin Boulevard Station, Queens Boulevard Line (IND), in the Borough of Queens of


Prospect Park Station, Brighton Beach Line (BMT),

in the Borough of Brooklyn

Contractor: Whitewood Renovations







Stair Repairs S2, M2, S5, M3 at 167th Street Station on Jerome Avenue Line (IRT), in the Borough of the Bronx


Contractor: B&R Construction Services Corp.












NYCT P.I.D. PROJECTS

NYCT Tier – 2 C-52161

Furnishing and Installing Passenger Identification (PID) CCTV at 49th St & 8th St stations, Broadway Line, Manhattan

Contractor: Static Electric Corp.








Furnishing and Installing Passenger Identification (PID) CCTV at 23rd St. and Rector St. Stations, Broadway Line, Manhattan

Contractor: Narula Development Corp.









Furnishing and Installing Passenger Identification (PID) CCTV at 135th Street Station, Lenox Ave Line, IRT Division, in the Borough of Manhattan

Contractor: Lion Heart Electric Corp.










Furnishing and Installing Passenger ID CCTV at 103rd Street Station, 8th Avenue Line, IND Division, in the Borough of Manhattan and at 138th Street-Grand Concourse Station, Jerome Avenue Line, IRT Division, in

the Borough of Bronx

Contractor: JAMCOB ELECTRIC LLC







FURNISHING AND
INSTALLING
PASSENGER
IDENTIFICATION (PID)
CCTV AT BROADWAY
STATION, CROSSTOWN
LINE, IND DIVISION, IN
THE BOROUGH OF
BROOKLYN AND AT
PELHAM PARKWAY
STATION, DYRE

AVE LINE, IRT DIVISION IN THE BOROUGH OF BRONX

Contractor: C.B. Mills Electric, LLC















FURNISHING
AND INSTALLING
PASSENGER
IDENTIFICATION
(PID) CCTV AT
MYRTLEWILLOUGHBY
STATION AND
FULTON ST.
STATION


Contractor: Tribeca Electrical Corp.











Furnishing and installing Passenger Identification

CCTV at Morgan Avenue Station, Canarsie Line,

BMT Division, in the Borough of Brooklyn

Contractor: C.B. Mills Electric, LLC















NYCT SYSTEMS DEMOLITION OF REMEDIATION SYSTEMS

Demolition of Remediation Systems at Flatbush Depot in the Borough of Brooklyn

Contractor:
Art2Live
Interior
Architecture
and Design LLC













Demolition of Remediation System at Kingsbridge Bus Depot int he Borough of Manhattan

Contractor: ABM Electric









NYCT COMMUNICATION ROOMS

NYCT Tier -1 C-43061R

Communication Rm Upgrade MR 115, 8th Ave./14TH St. Station, Canarsie Line (BMT), in the Borough of Manhattan

Contractor: Hard Rock Construction











NYCT Tier -1 C-43065R

Communication Room Upgrade, Clark Street Station, Clark Street Line, in the Borough of Brooklyn

Contractor: Clear It Out Contracting LLC













NYCT Tier -1 C-43069

Communication Rm Upgrade MR 115, 8th Ave./14TH St. Station, Canarsie Line (BMT), in the Borough of Manhattan

Contractor: Lambo Mechanical Inc







NYCT EMERGENCY EXITS


SBP NYCT Tier – 2 C-35320


Rehabilitation of Emergency Exit #210: South of

Prospect Park Station, Brighton Beach Line (BMT),

in the Borough of Brooklyn

Contractor: Madhu Construction Corp.













NYCT STATION VENTILATOR REPAIRS


NYCT Tier – 1 A-37384

Station
Ventilator
Repairs at 50th
Street Station,
Broadway/7th
Avenue Line
(IRT), Vent
Batteries H, I, J,
K, in the
Borough of
Manhattan

Contractor:
Doctor Power
Cooling &
Heating,
Incorporated







NYCT MASONRY REPAIRS

NYCT Op. 95674-1

Bergen Shop Masonry Work & Concrete Repair

Contractor: AM Restoration Inc.







NYCT ROOF REPAIRS


NYCT Op. 99057

Baychester Substation Roof Repair

Contractor: Benchmark Trading Corp










NYCT Op. 99039

Jamaica Yard Building 5 Roof Repair

Contractor: IQ Contracting, Inc. & Associates






NYCT DOB PROJECTS

B-40689

Chassis Wash and Platform Lift Upgrade at Ulmer Park Bus Depot (Tier 2)


Contractor: M.I.T. Brothers Construction, Inc



BN-19-0147

Rapid Rollup Door at Fresh Pond Depot, Queens


Contractor: Al Rasheed Group of Construction, Inc.



BS-20-003

Furnishing and Installation of Rapid Rollup Door at Ulmer Park Bus Depot, Booklyn


Contractor: Gidson Construction Inc.



C-40261

Replacement of Air Handling Equipment Phase 1 at Spring Creek Bus Dept (SBMP, Tier 2)


Contractor: V.I.V. Contracting Corp.



S-22-0003

Replace
Rapid Rollup
Door at
Charleston
Bus Depot,
Staten Island

Contractor: Allied Construction Corp.








BRIDGES & TUNNELS

AW-02S

Flood Mitigation at the Robert F. Kennedy Bridge, Robert Moses Building and Throgs Neck Bridge


Contractor: S&P Construction Management Inc.



HCM-387

Tunnel Ceiling Cleaning at Hugh L. Carey Tunnel (Tier 2)

Contractor:
Saheet
Construction,
Corp.



HCM-388

Tunnel
Preservation at
Hugh L. Carey
Tunnel

Contractor: Honey Construction, Inc.









QMM-371

Tunnel Ceiling
Cleaning at
Queens
Midtown
Tunnel (Tier 2)


Contractor: Oudaz General Contracting, Inc.



QMM-372

Tunnel
Preservation at
Queens
Midtown
Tunnel

Contractor: New York International Builders Corp.







VNM-410

Bridge Preservation at the Verrazano-Narrows Bridge (Tier 2)

Contractor: Honey Construction, Inc.



LONG ISLAND RAILROAD

LIRR 6400

Ronkonkoma Yard EIC Fit out and Storage Container Unit

Contractor: Bloom Construction










LIRR 6471

Atlantic Ave
Tunnel
Structural
Work at
Crescent Street
(SBFP)

Contractor: Malcolm Patrick Corp









LIRR 6477

Hillside
Building #1
Loading Dock
Repairs and
Pine Aire Yard
Asphalt Paving

Contractor: Floracon LLC

