

## **Table of Contents**

---

<b>List of Tables.....</b>	<b>vii</b>
<b>List of Figures .....</b>	<b>ix</b>
<b>Executive Summary.....</b>	<b>S-1</b>
<b>Chapter 1: Purpose and Need .....</b>	<b>1-1</b>
1.1    Introduction .....	1-1
1.2    Purpose and Need for the Proposed Project .....	1-1
1.2.1    MTA NYCT Goals and Objectives.....	1-2
1.2.2    Project-specific Goals and Objectives .....	1-2
1.3    Problem Identification .....	1-4
1.3.1    Station Conditions .....	1-4
1.3.2    Station Deficiencies.....	1-5
1.4    Analysis Framework, Environmental Process, and Required Reviews/Approvals.....	1-14
1.4.1    Analysis Framework .....	1-14
1.4.2    Environmental Process and Required Reviews/Approvals .....	1-14
<b>Chapter 2: Project Alternatives .....</b>	<b>2-1</b>
2.1    Introduction .....	2-1
2.2    Background .....	2-1
2.3    No-Build Alternative .....	2-13
2.4    Proposed Project.....	2-14
2.4.1    Street Level.....	2-14
2.4.2    Mezzanine Level Improvements at East 68th Street and East 69th Street.....	2-18
2.4.3    Evaluation of Vertical Access and Path of Travel .....	2-24
2.5    Anticipated Benefits with the Proposed Project .....	2-30
<b>Chapter 3: Social Conditions .....</b>	<b>3-1</b>
3.1    Introduction .....	3-1
3.2    Land Use, Zoning, and Public Policy.....	3-1
3.2.1    Methodology.....	3-1
3.2.2    Existing Conditions .....	3-2
3.2.3    Impacts and Mitigation .....	3-5
3.3    Business Impacts and Socioeconomic Conditions .....	3-7
3.3.1    Methodology.....	3-7
3.3.2    Existing Conditions .....	3-7
3.3.3    Impacts and Mitigation .....	3-7
3.4    Community Facilities and Services.....	3-8
3.4.1    Methodology.....	3-8
3.4.2    Existing Conditions .....	3-8

---

## **68<sup>th</sup> Street/Hunter College Subway Station Improvement Project EA**

---

3.4.3	Impacts and Mitigation .....	3-9
3.5	Open Space .....	3-10
3.5.1	Methodology.....	3-10
3.5.2	Existing Conditions .....	3-10
3.5.3	Impacts and Mitigation .....	3-10
3.6	Urban Design and Visual Resources.....	3-11
3.6.1	Methodology.....	3-11
3.6.2	Existing Conditions .....	3-12
3.6.3	Impacts and Mitigation .....	3-12
3.7	Public Health .....	3-13
3.8	Neighborhood Character .....	3-13
3.8.1	Existing Conditions .....	3-14
3.8.2	Impacts and Mitigation .....	3-14
3.9	Environmental Justice .....	3-15
<b>Chapter 4: Historic and Cultural Resources.....</b>		<b>4-1</b>
4.1	Introduction .....	4-1
4.2	Methodology.....	4-1
4.3	Existing Conditions.....	4-1
4.3.1	Archaeological Resources .....	4-1
4.3.2	Historic Architectural Resources.....	4-3
4.4	Impacts and mitigation .....	4-4
4.4.1	No-Build Alternative.....	4-4
4.4.2	Proposed Project .....	4-4
<b>Chapter 5: Transportation and Pedestrian Circulation.....</b>		<b>5-1</b>
5.1	Introduction .....	5-1
5.2	Traffic .....	5-2
5.2.1	Methodology.....	5-3
5.2.2	Existing Conditions .....	5-4
5.2.3	2020 Future No Build Conditions .....	5-5
5.2.4	2020 Build Conditions .....	5-5
5.3	Subway Transit.....	5-6
5.3.1	Methodology.....	5-7
5.3.2	Existing Conditions .....	5-8
5.3.3	2020 Future No Build .....	5-10
5.3.4	2020 Future Build .....	5-13
5.4	Bus Transit.....	5-17
5.4.1	Existing Conditions .....	5-17
5.4.2	2020 Future No-Build .....	5-18
5.4.3	2020 Future Build .....	5-18

---

## Table of Contents

5.5	Parking .....	5-19
5.5.1	Methodology.....	5-19
5.5.2	2020 Future No-Build .....	5-20
5.5.3	2020 Future Build .....	5-21
5.6	Pedestrian .....	5-22
5.6.1	Data Collection .....	5-22
5.6.2	Analysis Methodology.....	5-22
5.6.3	Impact Criteria.....	5-23
5.6.4	Existing Conditions .....	5-23
5.6.5	2020 Future No-Build Condition .....	5-25
5.6.6	2020 Future Build Condition .....	5-29
5.7	Conclusion.....	5-34
<b>Chapter 6 Air Quality .....</b>		<b>6-1</b>
6.1	Introduction .....	6-1
6.2	Regulatory Framework .....	6-1
6.2.1	National Ambient Air Quality Standards.....	6-1
6.2.2	Compliance Status.....	6-1
6.2.3	Transportation Conformity .....	6-1
6.3	Methodology.....	6-3
6.4	Existing Conditions.....	6-3
6.5	Mobile Sources .....	6-4
6.6	Stationary Sources .....	6-4
6.7	Congestion Mitigation and Air Quality Improvement Program.....	6-4
<b>Chapter 7 Noise and Vibration .....</b>		<b>7-1</b>
7.1	Noise .....	7-1
7.1.1	Methodology.....	7-1
7.1.2	Existing Conditions .....	7-1
7.2	Impacts and Mitigation .....	7-1
7.3	Vibration .....	7-2
<b>Chapter 8 Natural Resources .....</b>		<b>8-1</b>
8.1	Floodplains.....	8-1
8.2	Navigable Waterways .....	8-1
8.3	Wetlands and Coastal Zone .....	8-1
8.4	Protected Species .....	8-1
<b>Chapter 9 Contaminated Materials .....</b>		<b>9-1</b>
9.1	Introduction .....	9-1
9.2	Existing Conditions.....	9-1

9.2.1	Historical Information Sources.....	9-1
9.2.2	Regulatory Agency Information Sources.....	9-2
9.3	Impacts and Mitigation.....	9-2
9.3.1	No-Build Alternative.....	9-2
9.3.2	Proposed Project.....	9-2
<b>Chapter 10 Energy Requirements.....</b>		<b>10-1</b>
10.1	NYCT, ISO 14001, and New York State E.O. 88 .....	10-1
10.2	Existing Conditions.....	10-2
10.3	No-Build Alternative .....	10-2
10.4	Proposed Project.....	10-2
10.4.1	Construction.....	10-2
10.4.2	Operation .....	10-2
<b>Chapter 11 Safety and Security.....</b>		<b>11-1</b>
11.1	Existing Conditions.....	11-1
11.2	Safety and Security During Construction.....	11-1
11.3	No-Build Alternative .....	11-1
11.4	Proposed Project.....	11-1
<b>Chapter 12 Section 4(f) Resources .....</b>		<b>12-1</b>
12.1	Regulatory Framework .....	12-1
12.2	Identification and Description of Section 4(f) Resources .....	12-1
12.3	Impacts to Section 4(f) Resources .....	12-2
12.4	Section 4(f) <i>De Minimis</i> Finding .....	12-6
<b>Chapter 13 Construction .....</b>		<b>13-1</b>
13.1	Introduction .....	13-1
13.2	Construction Methods .....	13-1
13.3	Construction Phases .....	13-4
13.3.1	Phase 1 .....	13-4
13.3.2	Phase 2 .....	13-6
13.3.3	Phase 3 .....	13-7
13.4	Potential Construction Impacts .....	13-7
13.4.1	Social Conditions .....	13-7
13.4.2	Environmental Justice .....	13-9
13.4.3	Historical and Cultural Resources .....	13-9
13.4.4	Transportation and Pedestrian Circulation.....	13-9
13.4.5	Air Quality.....	13-13
13.4.6	Noise and Vibration.....	13-15
13.4.7	Contaminated Materials .....	13-17

---

## Table of Contents

13.4.8	Natural Resources .....	13-17
13.4.9	Energy.....	13-19
13.4.10	Utilities .....	13-19
<b>Chapter 14</b>	<b>Indirect and Cumulative Impacts .....</b>	<b>14-1</b>
14.1	Potential Indirect Impacts.....	14-1
14.2	Potentially Cumulative Impacts .....	14-1
<b>Chapter 15</b>	<b>Coordination .....</b>	<b>15-1</b>
15.1	Introduction .....	15-1
15.2	Regulatory Context .....	15-1
15.3	Approvals, Permits and Coordination .....	15-1
15.4	Agency Coordination.....	15-2
15.4.1	New York City Department of Transportation .....	15-2
15.4.2	New York City Department of Environmental Protection.....	15-3
15.4.3	New York City Department of Parks and Recreation .....	15-3
15.4.4	New York State Office of Parks, Recreation and Historic Preservation .....	15-3
15.4.5	New York City Landmarks Preservation Commission .....	15-3
15.5	Public Outreach.....	15-3
<b>Chapter 16</b>	<b>Agencies and Persons Contacted .....</b>	<b>16-1</b>
<b>Chapter 17</b>	<b>References .....</b>	<b>17-1</b>

## Appendices

Appendix A: Preliminary Alternatives Screening

Appendix B: Correspondence

Appendix C: Transportation Study

Appendix D: Station Congestion Photographs

Appendix E: Environmental Justice Data

This page intentionally left blank.

---

**List of Tables**

Table S-1: Comparison of Planning Alternatives Considered .....	S-9
Table 1-1: Existing/Future (2020) No-Build Platform Stair Clearance Time (Seconds).....	1-12
Table 1-2: Existing/Future (2020) No-Build LOS at East 68th Street Stairs* .....	1-13
Table 2-1: Existing and 2020 No-Build Clearance Times (seconds)—Platform Stairs.....	2-13
Table 2-2: Existing and 2020 No-Build LOS - Street Stairs .....	2-13
Table 2-3: Peak Clearance Times at Platform Stairs (Seconds).....	2-32
Table 2-4: No-Build and Build LOS at East 68th Street Stairs.....	2-32
Table 3-1: Schools and Public Facilities in the Study Area.....	3-9
Table 3-2: Street Trees on East 68th and 69th Streets between Third and Park Avenues.....	3-10
Table 4-1: Contributing Elements – Upper East Side Historic District .....	4-3
Table 5-1: 2011 Existing Conditions: Signalized Intersection Level of Service Lexington Avenue at East 69th Street .....	5-5
Table 5-2: 2020 No-Build Conditions: Signalized Intersection Level of Service Lexington Avenue at East 69th Street .....	5-5
Table 5-3: 2020 Build Conditions: Signalized Intersection Level of Service Lexington Avenue at East 69th Street .....	5-6
Table 5-4: 2011 Existing Conditions: Subway Street Stair Level of Service 68th Street/Hunter College Station.....	5-9
Table 5-5: 2011 Existing Conditions: Subway Platform Stairs Level of Service 68th Street/Hunter College Station.....	5-9
Table 5-6: 2011 Existing Conditions: Subway Control Area Level of Service 68th Street/Hunter College Station.....	5-10
Table 5-7: Projected Diversion of Passengers from 68th Street/Hunter College Station to Second Avenue Subway .....	5-11
Table 5-8: 2020 No-Build Conditions: Subway Street Stairs Level of Service 68th Street/Hunter College Station.....	5-11
Table 5-9: 2020 No-Build Conditions: Subway Platform Stairs Level of Service 68th Street/Hunter College Station.....	5-12
Table 5-10: 2020 No-Build Conditions Platform Stairs Clearance Times (Seconds) .....	5-13
Table 5-11: 2020 No-Build Conditions: Subway Control Area Level of Service 68th Street/Hunter College Station.....	5-13
Table 5-12: 2020 Build Conditions: Subway Street Stairs Level of Service 68th Street/Hunter College Station.....	5-14
Table 5-13: 2020 Build Conditions: Subway Platform Stairs Level of Service 68th Street/Hunter College Station.....	5-15
Table 5-14: 2020 Build Conditions Platform Stairs Clearance Times (Seconds) .....	5-16
Table 5-15: 2020 Build Conditions: Subway Control Area Level of Service 68th Street/Hunter College Station.....	5-17
Table 5-16: 2011 Existing Conditions: On-Street Parking Capacity Lexington Avenue at East 69th Street .....	5-20

## **68<sup>th</sup> Street/Hunter College Subway Station Improvement Project EA**

---

Table 5-17: 2011 Existing Conditions: On-Street Parking Spaces Occupied Lexington Avenue at East 69th Street.....	5-20
Table 5-18: 2020 No-Build Condition: On-Street Parking Capacity Lexington Avenue at East 69th Street.....	5-20
Table 5-19: 2020 No-Build Condition: On-Street Parking Spaces Occupied Lexington Avenue at East 69th Street.....	5-21
Table 5-20: 2020 Proposed Project Condition: On-Street Parking Capacity Lexington Avenue at East 69th Street.....	5-21
Table 5-21: 2020 Proposed Project Condition: On-Street Parking Spaces Occupied Lexington Avenue at East 69th Street.....	5-22
Table 5-22: 2011 Existing Conditions: Crosswalk Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-23
Table 5-23: 2011 Existing Conditions: Corner Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-24
Table 5-24: 2011 Existing Conditions: Sidewalk Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-25
Table 5-25: 2020 No-Build Conditions: Crosswalk Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-26
Table 5-26: 2020 No-Build Conditions: Corner Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-27
Table 5-27: 2020 No-Build Conditions: Sidewalk Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-28
Table 5-28: 2020 No-Build and Build Condition: Crosswalk Level of Service Lexington Avenue at East 68th Street and East 69th Street.....	5-30
Table 5-29: 2020 No-Build and Build Conditions: Corner Level of Service Lexington Avenue at East 68th Street and East 69th Street.....	5-31
Table 5-30: 2020 No Build and Build Conditions: Sidewalk Level of Service Lexington Avenue at East 68th Street and East 69th Street .....	5-33
Table 6-1: National and State Ambient Air Quality Standards .....	6-2
Table 6-2: Representative Monitored Ambient Air Quality Data (2011 - 2013).....	6-3
Table 15-1: Approvals, Permits, and Coordination Required .....	15-2

**List of Figures**

---

Figure S-1:	Project Location.....	S-3
Figure S-2:	Existing Street Level Plan.....	S-4
Figure S-3:	Street Level Plan – Proposed Project .....	S-17
Figure S-4:	Street Level Plan – Proposed Project with Option E1 .....	S-19
Figure S-5:	Mezzanine Level Plan at East 68th Street .....	S-20
Figure S-6:	Platform Level Plan – Proposed Project .....	S-22
Figure S-7:	Section View of Mid-Block Stair and Mezzanine – Proposed Project .....	S-23
Figure S-8:	Section View of East 69th Street – Proposed Project.....	S-24
Figure S-9:	Platform Level Plan – Proposed Project with Option E1 .....	S-25
Figure S-10:	Section View of East 69th Street – Proposed Project with Option E1.....	S-26
Figure 1-1:	Existing 68th Street Level Views.....	1-6
Figure 1-2:	NE Corner – 68th Street & Lexington Avenue .....	1-7
Figure 1-3:	NE Corner – 68th Street & Lexington Avenue .....	1-8
Figure 2-1:	No Build Alternative .....	2-2
Figure 2-2:	Alternative 1 .....	2-3
Figure 2-3:	Alternative 2 – Northern Access.....	2-4
Figure 2-4:	Alternative 3 .....	2-6
Figure 2-5:	Alternative 4 .....	2-7
Figure 2-6:	Alternative 2 – Proposed Project.....	2-9
Figure 2-7:	Street Stair Option W1 .....	2-10
Figure 2-8:	Street Stair Option E10 .....	2-11
Figure 2-9:	Street Stair Option E1 .....	2-12
Figure 2-10:	Street Level Plan – Proposed Project .....	2-15
Figure 2-11:	Street Level Plan – Proposed Project with Option E1 .....	2-16
Figure 2-12:	Street Tree Removal Plan .....	2-17
Figure 2-13:	Mezzanine Level Plan East 68th Street.....	2-20
Figure 2-14:	Street and Platform Stairs and Mezzanine, East 69th Street – Proposed Project.....	2-21
Figure 2-15:	Mid-Block Entrance – Proposed Project.....	2-22
Figure 2-16:	Section Along East 69th Street – Proposed Project with Option E1.....	2-23
Figure 2-17:	Existing Street Level.....	2-27
Figure 2-18:	Proposed Street Level.....	2-28
Figure 2-19:	Existing and Proposed Mezzanine Level.....	2-29
Figure 2-20:	Proposed Platform Level .....	2-31
Figure 3-1:	Land Use .....	3-3
Figure 4-1:	Archaeological and Architectural APE .....	4-2
Figure 12-1:	Thomas Hunter Hall Light Well Looking North .....	12-4
Figure 12-2:	Position of Louver on South Wall of Light Well.....	12-5
Figure 12-3:	Rendering of New Mid-Block Entrance in the Imperial House Apartments Building.....	12-6

## **68<sup>th</sup> Street/Hunter College Subway Station Improvement Project EA**

Figure 13-1:	Phased Location of Surface Construction Activity.....	13-2
Figure 13-2:	Phased Location of Subsurface Construction Activity .....	13-3
Figure 13-3:	Existing Project Area Utilities .....	13-21